



















































STANDARD METHOD FOR PRODUCTION AT BIG BAGS INTERNATIONAL PVT LTD

	Standard Production	Industrial Production	Hygiene Room Production	
			Level I	Level II
Ultrasonic Cut fabric during Weaving				
Ultrasonic Cut fabric during Cutting				
Airwash				
Metal Detection	O	O		
Illuminated table Control				
All Seams Outside	O			
Yarns Burned				
Production under climatic conditions				
Uniform				
FDA approved raw material usage				
Glass procedure				
Pest control				
Employee health record				
Insect quitters				
Plastic secured light bulbs				
Tables, carts and racks stainless steel				
No allowance to food in production areas				
Broken needle & scissors policy				

O: Optional



: Standard/ Available



Not Available